

Datasheet AR2 G1

- Up to 14 Discrete Inputs
- 10 Discrete Outputs
- Up to 2 x 0-10V Analog Inputs
- 1 PTC Temperature Sensor Input
- RS-485 port to connect to AR2
- 18...32VDC or 100...240VAC supply options, 18Vdc Auxiliary Supply
Out for discrete inputs